

VOGERTOWN ARDEN

WATERTOWN, MASS

ASSIFIED ASSIFIED



## WATERTOWN ARSENAL **LABORATORY**

## MEMORANDUM REPORT

NO. WAL 710/735

Metallurgical Examination of a Cast Turret Manufactured by

the American Stool Foundries

This document has been approved for public release and sale; its distribution is unlimited.

BY

B. PHRIPS Phy. Sci. Aide



UNCLASSIFIED

DATE 25 March 1945

WATERTOWN ABSEMAL Watertown, Mass.

Form No. SPOND-38 1 18 July 1944

Accession For						
NTIS	GRA&I	122				
DTIC	TAB					
Unannounced 🔲						
Justification						
Distribution/ Availability Codes						
·····	Avail an	a/or				
Dist	Specia	1				
A-1						

NCLASSIFIED 

MEMORANDUM REPORT NO. WAL 710

Final Report on Problem B-4.73

25 March 1945

Metallurgical Examination of a Cast Turret Manufactured by

the American Steel Foundries

ABSTRACT

Metallurgical examination of two specimens representing the thinnest and thickest sections (1" to 1-1/4" and 3" to 3-1/2" respectively) of an M4 Cast Turret, No. B171, produced by the American Steel Foundries, indicated that the properties of the two sections were a function of the ease with which they could be hardened by quenching. The thin section has been fully quenched out and has Q good impact strength at both room temperature and at -40 . The thick section has not been completely hardened through the section, as evidenced by the decreased impact strength at the center of the section when tested at -40°F. These results were corroborated by fracture tests. The impact properties of the heavy section are. however, deemed adequate to insure ductile behavior upon ballistic impact.

As requested by the Ordnance Research Center, Aberdeen , a metallurgical examination has been conducted on two samples of the cast turret No. B171 for the Medium Tank M4, manufactured by the american Steel Foundries, which was subjected to ballistic tests at the Ordnance Research Center, Aberdeen, and exhibited high resistance to penetration with the 37mm APM 74 projectiles. The samples were of two thicknesses and were numbered as follows: B1711-1-1/4" thick, and B1718-3-3-1/2" thick. It was requested that a comparison of the two samples be made in order to determine the relation of the quality of the two thicknesses of the cast turret.

1. APG 470.5/1025 - Wtn 470.5/8635(r), dated 14 February 1945.

UNCLASSIFIED

- 2. The metallurgical examination of the cast turnet consisted of the following tests:
  - a. Chemical analysis.
  - b. Brinell hardness survey.
  - c. Fracture tests.
  - d. V-notch Charpy tests.
  - e. Microscopic examination.
  - 3. The results of the metallurgical examination are as follows:
    - a. Chemical analysis.

This alloy content is believed too low for the complete hardening of a three inch section, even under the most drastic conditions of quenching.

b. Brinell hardness survey. Slices were cut from the fracture specimens and five Brinell hardness impressions were made on the cross-sections of each slice. The results are given below:

Sample No.	Range	Average	
B171A(1* thick)	223-235	231	
B171B(3# thick)	212-229	222	

- c. Fracture test. Both sections were notched and fractured under the forge hammer and were rated with respect to fibre and steel soundness. No. B171A (1" thick section) exhibited a fibrous fracture with some shrinkage throughout. No. B171B (3" thick section) had a predominately fibrous fracture with a crystalline area in the center covering approximately 10% of the total area. The thick section also exhibited some shrinkage areas throughout the fracture.
- d. V-notch Charpy impact tests. V-notch impact tests were made on samples machined from the centers of both sections. The results are given below:

Sample No.	Thickness of Section	+70°F.		-14O <b>₽.</b>	
		Ft./lbs.	Fracture Rating	Ft./1bs.	Fracture Rating
B1714	1-1/4"	45.8	*F*shrinkage.	42.0	***Cbf-1/4
B171A	1-1/4"	40.3	F+shrinkage.	36.6	Fc-1/3
		Ave. 43.1	r <b>A</b>	. 39-3	
3171B	3-1/2"	58 <b>.6</b>	**Fc-1/Weshrinkage.	29.5	361-9/10
B171B	3-1/2"	46.2	Fc-1/4+shrinkage.	27.3	Cbf-9/10
		Ave. 52.4	ra.	re. 28.4	

<sup>\*</sup>F- Fibrous

Sample No. B171B shows a decrease in impact energy when tested at -40°T. indicating that this section has not been completely hardened throughout.

- e. Microscopic examination. Photomicrographs illustrating the microstructure of both sections of the cast turnet are shown in Figure 1. Section No. B171A (1-1/4" thick) had a microstructure similar to tempered bainite associated with fine carbides. Section No. B171B (3" thick) exhibits a considerable amount of ferrite and a structure similar to tempered bainite and fine carbides.
- 4. The results of this investigation indicate that the american Steel Foundries cast turnet No. B171 had good metallurgical properties, the thinner section (No. B171A) being fully quench hardened, whereas the thicker 3" section was not completely hardened throughout.

B. Phelps

B. Phelps
Phy. Sci. Aide

APPROVAD:

E. L. REED

Research Metallurgist


Acting Chief, Armor Section

<sup>\*\*</sup>Fc - Fibrous matrix with spots of crystallinity. Fracture refers to amount of crystallinity.


<sup>\*\*\*</sup>Cbf - Bright crystalline patch surrounced by fibrous border.

## Microstructure of Cast Turret No. B171 Manufactured by

the American Steel Foundries



No. B171a X1000 Picral Structure similar to tempered bainite associated with fine carbides.



No. B171: X1000 Picral Structure similar to tempered bainite associated with fine carbides and ferrite patches.

をおかれる。 「おかないない。」 「いったいか」 「いったいか。 「いったいか」 「いったいか」 「いったいか。 「いったい。 「いったい。 「いったい。 「いったい。 「いったい。 「いったい。 「いったい。 「いったい。 「いったい。 「いったい。